

Notice to Mariners

Ormonde Offshore Wind Farm – Export Cable May 2017

Mariners are notified of planned cable repair works on the **Ormonde Offshore Wind Farm export cable**. The works are planned to take place within the area shown in Figure 1. The main cable repair vessel that will be present on site during the works will be the *Stemat 82* - see right.



Mariners are requested to observe a voluntary 200m Anchor/Trawling Exclusion Zone around this location and also ensure that due caution is exercised at all times in these areas.

A Fisheries Liaison Officer (FLO) has been appointed for the duration of the works. Contact details are provided below.

Any questions relating to the cable areas mentioned in this NtM should be directed to:

Jonny Lewis	E: jonny.lewis@marinespace.co.uk
Environmental & Consents Adviser	
TC Ormonde OFTO Ltd	M: 07817 644284

Figure 1 Location of planned export cable repair works at Ormonde OWF Ormonde OWF Export Cable Cable Fault Repair Work Boundary 500m Approximate Buffer from Anchor Points Anchor Boundary (500m Approx. Buffer)

Approximate Anchor Points

X Turbine Locations

Estimated Calculated Fault Position Ormonde OWF OSP Polyline Ormonde OWF Export Cable RPL 2016 Mainland UK
Ormonde OWF Area 5991000 WGS84 UTM 30N WGS84 DMS LAT LONG Point ID X 472737.5 5990819.3 54° 03' 53.530N 003° 24' 59.600W Ge@-4D 474745.0 5991641.7 54° 04' 20.506N 003° 23' 09.424W 471883.8 5992903.2 54° 05' 00.787N | 003° 25' 47.253W
 Date
 Rev
 Drawn
 Checked
 File
 Page

 7/04/2017
 R0
 JD
 BC
 P1068-DW-C13-R0
 1 of 1
 473891.3 5993725.5 54° 05' 27.774N | 003° 23' 57.037W 472000 473000 475000