

NOTICE TO MARINERS

Sent: 22 January 2019 12:08

Subject: BURBO BANK 2 (EXTENSION) - WAVE RIDER BUOY ANCHOR AND CHAIN LOST ON SEABED

Dear All,

During the recovery of the Wave Buoy North at BURBO BANK 2 (EXTENSION) the anchor weight and a 6 meter section of the mooring chain was lost overboard.

The combined weight of the anchor and chain is approx. 800 Kg

The lost anchor weight and section of chain is reported as being at position :

Lat 53° 30.11' N Lon 003° 21.95' W

This position is roughly in the area between Turbine positions A01 and B01 on the attached 'Kingfisher Awareness Chart'

Steps are being taken to determine the next actions but meanwhile fishermen are requested and advised to mark the above position on their charts/Plotters and keep clear until informed that the objects have been removed

Please note that 'Kingfisher Awareness Chart' is provided for information purposes relating to the Wind Farm only and should not be used for navigation

.....

Please do not hesitate to contact me if you are unsure about any of the above or require any further information, also please pass this information to any of your colleagues who you think might be interested.

If you know of any fisherman who works the area and does not receive this information or anybody else who would benefit from this information please let me know.

Regards : Tom Watson

Tel..... Mobile 07903 173 624

Home 01253 875565