



# Walney Extension

## WOW03+04 Export Cable Area of Operations

- Area of Operations Coordinates
- Area of Operations
- WOW03+04 OFTO Phase Areas 20161005
- WOW03+04 As-Laid Export Cable
- WDS01 Offshore Export Cable
- BOW01 Offshore Export Cable



Coordinate system: ETRS 1989 UTM Zone 30N  
 Scale@A4: 1:5000  
 0 100 200 Metres

REV	REMARK	DATE
---	First Issue	01/05/2018